



- NOTES:**
1. DEVICES WITHIN THE DASHED LINES ARE AN INTEGRAL PART OF THE FERRUPS UPS.
 2. A TERMINAL \square IS ASSIGNED THE NUMBER OF THE WIRE CONNECTED TO IT.
 3. A WIRE NO. IS SHOWN ONLY ONCE PER COLUMN, UNLESS IT CROSSES TO ANOTHER COLUMN, OR IF ADDITIONAL NUMBERS ARE NECESSARY FOR CLARITY.
 4. LINE NUMBER DENOTES BOTH SHEET NUMBER AND LINE NUMBER.
e.g. LINE NO. 113 IS ON SHEET 1, LINE 13

INTEGRAL CONTROL SYSTEM SERVICES, INC.

ICSS

1303 SACKETT AVENUE
Cuyahoga Falls, Ohio 44223

Office: 330-923-6900 Fax: 330-923-2116

THIS DRAWING IS THE PROPERTY OF INTEGRAL CONTROL SYSTEM SERVICES, INC. NEITHER THE DRAWING, NOR REPRODUCTIONS OF IT, NOR INFORMATION DERIVED FROM IT IS TO BE GIVEN TO OTHERS. NO USE IS TO BE MADE OF IT WHICH IS OR MAY BE INJURIOUS TO INTEGRAL CONTROL SYSTEM SERVICES, INC.

TITLE: UPS SYSTEM - REMOTE STATUS WIRING SCHEMATIC

REV	DATE	CHANGE	CUSTOMER:
			JOB: DATE:
			DRAWN BY: LA APRVD. BY: MM
			SHEET No: SHEET 1 OF 1
			Dwg. No: 080598-1